

MANUFACTURER:

DATE PREPARED:

Western Excelsior Corporation P.O. Box 659 90 1 Grand Avenue Mancos, CO 81328 (970-533-7412) 06/01/2011

MATERIAL SAFETY DATA SHEET

PRODUCT NAME:

ASPEN EXCELSIOR LOGS

WOOD FIBER EXCELSIOR SEDIMENT CONTROL LOG/TUBE/WATTLE

CHEMICAL FAMILY: CAS. NO. 8003-70-0 POLYETHYLENE & ORGANIC

OSHA HAZARD: NO

DESCRIPTION:

MACHINE PRODUCED MATRIX OF CURLED ASPEN WOOD EXCELSIOR ENCAPSULATED WITHIN EXTRUDED POLYPROPYLENE NET (TIED ON ENDS).

CAUTION: MOLTEN MATERIAL WILL PRODUCE THERMAL BURNS

PHYSICAL DATA

APPEARANCE & ODOR: WOOD EXCELSIOR FIBER, EXTRUDED PLASTIC MESH & POLYPROPYLENE AND/OR POLYETHELYNE THREAD. MILD ODOR

SOLUBILITY IN WATER: NEGLIGILBE

MELTING POINT: 285 – 300 DEGREES F

SPECIFIC GRAVITY: VARIABLE (DEPENDANT ON MOISTURE CONTENT)

Document # WE_EXCEL_SD3_MSDS Property of Western Excelsior Page 1 of 3 % VOLATILE BY VOLUME: N/A

PH:

FIRE AND EXPLOSION DATA

FLASH POINT: >600 DEGREES F

AUTOIGNITION > 400 - 500 DEGREES F TEMPERATURE :

EXPLOSIVE LIMITS IN AIR: N/A

EXTINGUISHING MEDIA: WATER SPRAY, DRY CHEMICAL

5

SPECIAL FIRE FIGHTING PROCEDURES: SPRAY WITH WATER. WEAR SCBA AND PROTECTIVE CLOTHING TO PREVENT CONTACT WITH SKIN

UNUSUAL FIRE &STRONG TO SEVERE (if blanket comes in
contact with ignition source)

REACTIVITY DATA

STABILITY:

STABLE

INCOMPATIBILITY: AVOID CONTACT WITH OXIDIZING AGENTS, DRYING OILS, FLAME, TEMPERATLTRES OVER 400 DEGREES F

POLYMERIZATION:

HAZARDOUS DECOMPOSITION PRODUCTS: COMBUSTION WILL PRODUCE CARBON DIOXIDE, CARBON MONOXIDE, ALDEHYDES, & INORGANIC ACIDS.

HEALTH HAZARDS

NO SPECIFIC HAZARD

WILL NOT OCCUR

EXPOSURE LIMITS:

N/A

EYE CONTACT:

SKIN CONTACT:

MOLTEN MATERIAL WILL PRODUCE THERMAL BURNS

Document # WE_EXCEL_SD3_MSDS Property of Western Excelsior Page 2 of 3 **INGESTION:**

LOW HAZARD

INHALATION: MAY CAUSE NASAL DRYNESS, IRRITATION AND OBSTRUCTION

EMERGENCY FIRST AID PROCEDURES

INGESTION: REMOVE TO FRESH AIR. GET MEDICAL ATTENTION, IF DIFFICULTY IN BREATHING OCCURS

EYE CONTACT: N/A

EYE CONTACT: WASH WITH WATER, IF IRRITATION DEVELOPS GET MEDICAL ATTENTION

SKIN CONTACT: IF BURNED BY CONTACT WITH MOLTEN MATERIAL, COOL QUICKLY AND GET MEDICAL ATTENTION

NOTE TO PHYSICIAN: BURNS SHOULD BE TREATED AS THERMAL BURNS. PLASTIC WILL COME OFF AS HEALING OCCURS.

SPILL AND LEAK PROCEDURES

REMOVAL AND DISPOSAL

CLEAN UP AND INCINERATE OR BURY ACCORDING TO FEDERAL, STATE AND LOCAL REGULATIONS

SPECIAL PRECAUTIONS

IN ACCORDANCE WITH GOOD INDUSTRIAL PRACTICES, HANDLE WITH CARE, AVOID CONTACT WITH OXIDIZING MATERIALS AND PROVIDE VENTILATION.

The information and data herein are believed to be accurate and have been compiled from sources believed to be reliable. There is no warranty of any kind, express or implied, concerning the accuracy or completeness of the information and data herein.